

# Manhole Inspection Summary

Manhole # S04CC2011MH

Printed On: 12/17/2008

Page 1 of 3

**Inspection** ☐ Is Incomplete Rating: **3) Fair**

Record Plat: **04CC2** Node: **011** Status: **Found**

Insp Date: **8/9/06 12:00 AM**

Incomplete Comments

Crew: **CH, IJ**  
Inspector: **Hale, C**  
Firm: **RKK**

**Location** Address: **3501 CROSS COUNTRY BLVD** Cross Street: **LABYRINTH RD**

**Manhole** Type: **Overflow** Location: **Grass** Ground Conditions: **Dry**  
☐ Prev. Rehab Weather: **Dry** Subject To Ponding: **None**

Comments **The O12 is cemented shut - there still appears to be infiltration.**

**Cover** Shape: **Circular** Diameter: **30** (in.) Length: (in.) Dist A/B Grade: **4** (in.)  
Type: **Stormwater** Condition: **Sound** Cover Material: **Cast Iron**  
Properties: ☐ Bolted ☐ Vented ☐ Water Tight ☐ Water Tight Insert

**Frame** Offset: **0** (in.) Condition: ☒ Sound ☐ Cracked ☐ Leaks

**Chimney / Frame Adjustment** ☐ Exists Material: ☐ Parged Height: (in.)  
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated  
Infiltration: ☐ None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall

**Corbel** Material: **Brick** ☐ Parged Type: **Concentric/Eccentric**  
Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated  
Infiltration: ☐ None ☒ **Joint** ☐ Cracks ☒ **Mortar** ☐ Roots ☐ Wall

**Barrel** Material: **Brick** ☐ Parged  
Shape: **Circular** Diameter: **42** (in.) Length: (in.)  
Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ☐ Deteriorated  
Infiltration: ☐ None ☐ Joint ☐ Cracks ☒ **Mortar** ☐ Roots ☒ **Wall**

**Bench** ☒ Exists Material: **Brick** ☐ Parged ☒ **Debris** (not Condition related)  
Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

**Channel** Material: **Brick** ☐ Parged ☒ **Debris** (not Condition related)  
Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:  
Condition: ☒ Sound ☐ Cracked ☐ Root Intrusion ☐ Deteriorated ☐ Leaks ☐ Debris

**Steps** Count: **0** Missing: **0** ☐ Corroded

**Surcharge** ☐ Evidence Of Surcharge Depth: (ft.) ☐ Active Surcharge Present

Location View



Top View



Corbel and Barrel infiltration. Bench debris. Channel debris.

# Manhole Inspection Summary

Manhole # S04CC2011MH

Printed On: 12/17/2008

Page 3 of 3

## Pipe Out @ 12 O'Clock



Cemented pipe.

Pipe Material: ☐ Pipe Lined  
Invert Depth: (ft.) Flow Characteristics: **None**  
Deposits: ☐ None ☒ **Mud** ☐ Sludge ☐ **Debris** ☐ Grease  
Silt Depth: **2** (in.) Deposits Extent: **Light**  
Infiltration: **None** Pipe Seal Cond: **Unknown**

Drop:		
Angled:	Reading:	(ft.)
	Inv Depth:	(ft.)
Drop Condition:		

Connects To: **Stub connection / abandoned**  
☐ Possible Illicit Connection

## Pipe In @ 6 O'Clock



Pipe Material: ☐ Pipe Lined  
Invert Depth: (ft.) Flow Characteristics: **None**  
Deposits: ☐ None ☒ **Mud** ☐ Sludge ☒ **Debris** ☐ Grease  
Silt Depth: **1** (in.) Deposits Extent: **Light**  
Infiltration: **Evidence** Pipe Seal Cond: **Unknown**

Drop:		
Angled:	Reading:	(ft.)
	Inv Depth:	(ft.)
Drop Condition:		

Connects To: **Stub connection / abandoned**  
☐ Possible Illicit Connection